BEDFORD, OHIO 44146

9636

CERTIFICATE OF INSPECTION

VALID FOR ONE YEAR

Address: 824 Archer Road Date: December 22, 2015

Perm. Parcel No: 813-29-060 Use District:

Present Occupancy: 1 Dwelling Unit Permitted Occupancy: 1 Dwelling Unit

Owners Name: Wayne and Candy Sanford 6 persons Maximum Occupancy:

Mail to: same Property: Legal Conforming [X]

Legal Non-Conforming []

Illegal []

Upon inspection, we find that said property is in need of repairs as follows:

GENERAL PLUMBING ITEMS:

1. Hot water tanks must be equipped with a listed \(\frac{1}{4} \)-turn gas shut-off valve and dirt leg on gas line. Install the gas valve at the hot water tank.

1ST AND 2ND FLOOR - BATH ITEMS:

1. Caulk base of each toilet leaving 1/2" in rear without caulk.

THE CITY REQUIRES VERIFICATION THAT ALL ASSESSMENTS FROM THE CITY OF BEDFORD FINANCE DEPARTMENT (440-735-6504) HAVE BEEN ACKNOWLEDGED AND WILL BE PAID. VERIFICATION MAY BE ACCOMPLISHED BY SHOWING THAT THE SPECIAL ASSESSMENT AMOUNT DUE IS BEING HELD IN AN ESCROW ACCOUNT. THIS IS REQUIRED PRIOR TO ISSUANCE OF THE C/O FOR TITLE TRANSFER

This dwelling unit has been measured and determined to be approved for a maximum of SIX (6) occupants (total of both adults and children)

NOTICE: THIS IS A VISUAL INSPECTION. THE CITY ASSUMES NO LIABILITY OR RESPONSIBILITY FOR FAILURE TO REPORT VIOLATIONS THAT MAY EXIST AND MAKES NO GUARANTEE WHATSOEVER THAT FUTURE VIOLATIONS CANNOT, OR WILL NOT OCCUR.

NOTICE

Violations identified as **HEALTH/SAFETY**, must be corrected/inspected **PRIOR** to occupancy. Violations identified as **REQUIRED MAINTENANCE VIOLATIONS**, must be corrected and inspected no later than SIX MONTHS from date of transfer (weather permitting). An escrow account shall be established with an amount of money equal to 150% of the value of the work required to correct **ALL** outstanding violations.

Corrections will be the responsibility of the individual named on the Escrow Hold Statement.

PERMITS ARE REQUIRED FOR HVAC. PLUMBING, ELECTRICAL AND MAJOR CARPENTRY.

CITY OF	REDEORD	RIIII DING	DEPARTME	UT

Inspector: Robert Brown